Kawasaki VERSYS 650 2006-2025

FITTING INSTRUCTIONS TO BE FITTED BY A QUALIFIED TECHNICIAN




THIS SHEET INCLUDES FITTING INSTRUCTIONS FOR THE FOLLOWING PARTS:

 $Secondary\ Alternator\ Cover\ Part\ No.\ EC-ER6-2006-1-GBR\ /\ Secondary\ Clutch\ Cover\ Part\ No.\ EC-ER6-2006-2-GBR\ /\ Secondary\ Pulse\ Cover\ Part\ No.\ EC-ER6-2006-3-GBR\ /\ Secondary\ Pulse\ Cover\ P$

SECONDARY ALTERNATOR COVER PART NO. EC-ER6-2006-1-GBR

- 1 Remove lower fairing.
- 2 Remove 4 existing bolts from the Alternator cover, shown as position Bolt 1, 2, 3 & 4. Note cable bracket at position 4.
- 3 Place the Secondary Clutch Cover over the stock cover.
- 4 Assemble 4 replacement bolts loosely in the correct position as shown. Note: Must use thread lock. Bolt 3 is M6 X 50HHF. Ensure that the cable bracket is aligned correctly at position 4.
- 5 Tighten bolts to a Torque of 11Nm as per Manufacturer's recommendations. DO NOT OVERTIGHTEN.







SECONDARY CLUTCH COVER PART NO. EC-ER6-2006-2-GBR


- 1 Remove lower fairing.
- 2 Remove 3 existing bolts from the Clutch cover, shown as position Bolt 1, 2 & 3.
- 3 Place the Secondary Clutch Cover over the stock cover.
- 4 Assemble 3 replacement bolts loosely in the correct position as shown.

Note: Must use thread lock

5 Tighten bolts to a Torque of 11Nm as per Manufacturer's recommendations.
DO NOT OVERTIGHTEN.







SECONDARY PULSE COVER PART NO. EC-ER6-2006-3-GBR

- 1 Remove lower fairing.
- 2 Remove 3 existing bolts from the Pulse cover, shown as position Bolt 1, 2 & 3.
- 3 Place the Secondary Pulse Cover over the stock cover.
- 4 Assemble 3 replacement bolts loosely in the correct position as shown.

Note: Must use thread lock

5 Tighten bolts to a Torque of 11Nm as per Manufacturer's recommendations. DO NOT OVERTIGHTEN.







Protection Bundle: CP-ER6-2006-CS-GBR

EC-ER6-2006-1-GBR, EC-ER6-2006-2-GBR, EC-ER6-2006-3-GBR, CGA09-GBR, BA12-10-GBR-SET

www.**GB**Racing.eu